

#3519
December 17, 2019
Page 1 of 1

SUBJECT: P/N 29546675 — 4th Generation A46 TCM Product Discontinuation

MODELS AFFECTED: Various

Introduction:

The 4th Generation A46 TCM will no longer be offered by Allison Transmission.

Serviceability:

To continue servicing vehicles, customers will need to go to a local GM Dealer to purchase the 4th Generation A46 TCM equivalent, GM's T14A TCM (P/N 24256864). Allison TCM Reflash™ V6.2 is needed to reflash the GM T14A TCM.

Old Part Number	Supplier	New Part Number	Supplier
29546675 – A46	Allison Transmission	24256864 – T14A	General Motors

In order to install the correct calibration in the new TCM, please contact your nearest Allison authorized distributor via the Sales and Service locator at www.allisontransmission.com. The new TCM will need to be taken to the location in order to be Reflashed with the correct calibration. Charges may apply for this additional required service.