

Revisions to this document are noted by a stripe in the left-hand margin.

#2701B  
Page 1 of 1

SUBJECT: Release of AT Shallow Sump Oil Filter Kit, P/N 29540976

EQUIPMENT AFFECTED: All AT 500 Model Transmissions With 3.8 Inch Shallow Oil Pan

AFFECTED SERIAL NUMBER: S/N 3210622842

### **Introduction:**

On January 1, 1993, a brass screen sump filter was released into all AT 500 Series transmissions. In March 2001, a new improved media sump filter was implemented into production for all AT 500 transmissions with the 5.3 inch deep oil pan (reference #901B). All AT 500 Series transmissions utilizing the 3.8 inch shallow oil pan will now use filter kit P/N 29540976, and continue to use the brass screen filter.

### **Interchangeability:**

This filter kit should **only** be used in AT 500 Series transmissions with the 3.8 inch (shallow) oil pan.

**NOTE: When servicing an AT transmission with the 5.3 inch (deep) oil pan, the current filter kit P/N 29538489 must be used.**

Existing stock of former filter kit P/N 29506392 should be utilized for servicing only AT 500 Series transmissions with the 3.8 inch (shallow) oil pan until the new filter kit P/N 29540976 is available.

### **Service Parts Information:**

The proper service kit for AT Series transmissions with the 3.8 inch (shallow) oil pan is P/N 29540976.

1	29503617	Brass Screen Filter
1	6771005	Sealring
1	29501160	Oil Pan Gasket

### **Fluid/Filter Change Intervals:**

The recommended fluid and filter change intervals (Non-TranSynd™ Fluid) and (TranSynd™ Fluid) for AT 500 Series transmissions are found in the latest revision of Service Tip #1099.

KH / SL4783EN

Allison Transmission, Inc.  
Indianapolis, Indiana 46206-0894

Copyright 2007 Allison Transmission, Inc. All Rights Reserved.