

Revisions to this document are noted by a stripe in the left-hand margin

#2701, Rev. B
July, 2006
Product Code(s): 32
Page 1 of 1

SUBJECT: Release of AT Shallow Sump Oil Filter Kit, P/N 29540976

MODELS AFFECTED: All AT 500 Model Transmissions With 3.8 Inch Shallow Oil Pan

SERIAL NUMBERS AFFECTED: 3210622842

Introduction:

On January 1, 1993, a brass screen sump filter was released into all AT 500 Series transmissions. In March 2001, a new improved media sump filter was implemented into production for all AT 500 transmissions with the 5.3 inch deep oil pan (reference SIL 9-TR-01 Rev. B). All AT 500 Series transmissions utilizing the 3.8 inch shallow oil pan will now use filter kit P/N 29540976, and continue to use the brass screen filter.

Interchangeability:

This filter kit should **only** be used in AT 500 Series transmissions with the 3.8 inch (shallow) oil pan.



NOTE: When servicing an AT transmission with the 5.3 inch (deep) oil pan, the current filter kit P/N 29538489 *must be used*.

Service Parts Information:

The proper service kit for AT Series transmissions with the 3.8 inch (shallow) oil pan is P/N 29540976.

| | | |
|---|----------|---------------------|
| 1 | 29503617 | Brass Screen Filter |
| 1 | 6771005 | Sealring |
| 1 | 29501160 | Oil Pan Gasket |

Fluid/Filter Change Intervals:

The recommended fluid and filter change intervals (Non-TranSynd® Fluid) and (TranSynd® Fluid) for AT 500 Series transmissions are found in the latest revision of SIL 10-TR-99.